

Inorganics in Impinger Solution

Analyte	EPA Methods			
Fluoride	13A	13B	14	14A
Hydrogen Chloride	26	26A		
Hydrogen Fluoride	26	26A		
Oxides of Nitrogen	7	7A	7B	
Sulfur Dioxide	6	6A	8	
Sulfuric Acid Mist	8			

Metals on Glass Fiber Filters

Analyte	EPA Methods			
Antimony	29		ALT-006	
Arsenic	29		ALT-006	
Barium	29		ALT-006	
Beryllium	29		ALT-006	
Cadmium	29		ALT-006	
Chromium	29		ALT-006	
Cobalt	29		ALT-006	
Copper	29		ALT-006	
Lead	29	12	ALT-006	
Manganese	29		ALT-006	
Mercury	29		ALT-006	
Nickel	29		ALT-006	
Selenium	29		ALT-006	
Silver	29		ALT-006	
Thallium	29		ALT-006	
Zinc	29		ALT-006	

Metals in Impinger Solution

Analyte	EPA Methods			
Antimony	29		ALT-006	
Arsenic	29		ALT-006	
Barium	29		ALT-006	
Beryllium	29		ALT-006	
Cadmium	29		ALT-006	
Chromium	29		ALT-006	
Cobalt	29		ALT-006	
Copper	29		ALT-006	
Lead	29	12	ALT-006	
Manganese	29		ALT-006	
Mercury	29	101A	ALT-006	
Nickel	29		ALT-006	
Selenium	29		ALT-006	
Silver	29		ALT-006	
Thallium	29		ALT-006	
Zinc	29		ALT-006	